

## **WATKINS REC LEAD WATER TEST RESULTS**

May 16th, 2016

1			
Δ	lev	7	tΔ
	IU 1	/ 💌	u

<b>Building Location</b>	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 WATKINS RECREATION CENTER	5/20/2016	WS- 012653	Classroom	1	In rec office adjacent to cafeteria	WT-042916-12670- A	< 2	WT-042916-12670- B	< 2				
					In hallway adjacent to rec center office								
2 WATKINS RECREATION CENTER	5/20/2016	WS- 012654	Cooler	1	manager	WT-042916-12671- A	< 2	WT-042916-12671- B	< 2				

## Footnotes:

- A First draw sample is collected after the plumbing system has not been used for at least 6 hours. B Second draw sample is collected after a 60 second flush at that device after the first draw.